


RevNo	Revision note	Date	Signature	Checked
A	Initial Release	17/01/08		
B	DIM E5 CHANGE FROM 82.2 TO 90.2 FROM HANDLE SUPPLIER CHANGE	19/05/09	FC	
C	Reduce Length of Profile by 1MM to 920mm, overlap issues in tool	08/05/13	FC	
D	Reduce Lid Overhang line 1351 to 721 to correct error see note3. Add Handle locators see note3. Slight amend to handle grip position having seen by the	24/02/14	FC	

# 10 LTR PAINT IML CUTTER PROFILE



- NOTES
1. DIMENSIONS IN MM
  2. NO TEXT TO APPEAR ABOVE THIS LINE AS LID OVERHANG WILL HIDE IT
  3. NO TEXT OR GRAPHICS TO APPEAR INSIDE AREA SHOWN AS HANDLE LOCATORS ARE PRESENT IN AT THESE POSITIONS

Itemref	Quantity	Title/Name, designation, material, dimension etc	Article No./Reference		
Designed by FC	Checked by LDEJ	Approved by - date FC - 08/05/13	Filename 10 LTR IML	Date 24/02/15	Scale 1:1
<b>10 LTR PAINT CUTTER PROFILE</b>					
336			Edition D	Sheet 1/1	